

Task – T2305337
Bars for Offshore Mooring Chain/Accessory
Manufacturer Approval - Renewal
Certificate No. OMC-T2305337 and
QA-5390725

Attention: Monica Jorrin, REINOSA FORGINGS & CASTINGS, S.L. (469223)

The documents shown in the attached list are reviewed or filed for reference in accordance with the applicable requirements of the following and the facility is considered approved to manufacture bars for offshore mooring chain/accessory as outlined in the process/product approval.

- 1. ABS Offshore Mooring Chain Guide (2017)
- 2. ABS Rules for Materials and Welding Part 2 (2022)

Please note it is the responsibility of the facility to inform ABS of any changes to the manufacturing parameters and request periodic quality audits or renewal of approval prior to the five year expiry date.

For any clarifications, contact Nikos Vrellos at +31 682 749049, <a href="mailto:nvrellos@eagle.org">nvrellos@eagle.org</a>.

Very truly yours,

Wei-Biao (Bill) Shi Vice President

Electronically Signed by: Satya Meruva

## **Documents List**

Drawing No.	Rev. No.	Title	Status
PO Renewal Certificate_Signed Application	-	Supporting Information	Filed by ABS for Reference Only
Correspondence	-	Request for OMC and QA Approval	Correspondence
IQNetES-0920	-	QA Certificate	Filed by ABS for Reference Only
RFC-MNU-TQ- 0001_REVe1	-	QA Manual	Reviewed
Material Certificates	-	Statistics	Filed by ABS for Reference Only
Correspondence	-	Approval Range	Correspondence
Carta Cambio de Nombre	-	No Changes Declaration	Reviewed
NCR Confirmation	-	No NCRs	Reviewed
Client Correspondence	-	Production Confirmation	Correspondence

An electronic copy of the documents appropriately stamped will be returned by FTP/e-mail.

## Process/Product Approval

Product	Grade	Maximum Diameter	Fine Grain Practice	Casting Practice
Forged Stock	R3	500 mm	AI+V	
	R3S			Ingot Casting
	R4			
	R4S			
Forged Stock	R5	745 mm	AI+V	Ingot Casting

Steel Making Practice: EAF
Deoxidation Practice: Aluminum
Heat treatment Facility: In-house

Offshore Mooring Chain/Accessory Manufacturer: VICINAY MOORING

CONNECTORS, S.A. (WCN 469971)

Note: Weld repair is generally not permitted, unless specially approved by the ABS

Engineering Office.

Include: Manufacturer Approval Certificate (OMC-T2305337) and QA Certificate (QA-5390725)